2017 MERCEDES-BENZ 519 CDI SPRINTER XLWB



Technical Specifications



Stock No: #TAG146	Year Model: 2017/01/19
Make: Mercedes-Benz	Previous Owners: 3
Model: 519 CDI Sprinter XLWB	Mileage: 329 719km (As per Odometer)
ast Service: N/A Next Service: N/A	
Previously Used For: Military Contract	

Selling Price: R499 000,00 VAT Incl.

Operating Cost:

<u> </u>	
Yearly License Fee (Estimate):	R 1992 +/-
Full Tank of Diesel:	R1930 +/-
Insurance P/M (Estimate):	R1800,00 +/-
General Service Cost:	R6 300,00 +/- (Own Service)

Engine:

Make:	Mercedes-Benz (OM642) CDI
Model Configuration:	6-Cylinder V6
Capacity:	2987 сс
Max Power (kW @ revs/min)	140kW (190hp) @ 3800rpm
Max Torquen(Nm @ revs/min)	440Nm @ 1400-2400rpm

Gearbox:

Make:	7G-TRONIC
No. Of Gears:	7-Speed (Automatic)
Retarder:	No
Retarder Make:	N/A

Interior Specifications:

Seating Capacity:	22 + Driver
Standing Capacity:	0
Seat Material:	Cloth
Seat Belts:	Yes
Parcel Shelves:	Yes
Radio:	Yes
P/A System	Yes
Rear View Camera	Yes
Reverse Buzzer:	No
Destination Board:	No
Passenger Door Type:	Sliding Door
Windows:	Opening - Sliding Windows
A/C Unit:	Yes
Underfloor Luggage Compartment:	No
Tow Bar:	Yes
Safe Stop:	No

Fuel Tank Capacity:

Type:	Plastic
-------	---------

Mass Data:

Manufacturer's Gross Vehicle Mass:	5000kg
Tare Weight:	3300kg
Permissible Maximum Front Axle Mass:	1850kg
Permissible Maximum Rear Axle Mass:	3500kg

Tyres:

	Make:	Tyre Depth:
Right Side Steer:	Tracmax	3.50mm
Left Side Steer:	Transporter RF09	1.74mm - Must Replace
Right Side Drive Inner:	Tracmax	1.82mm - Must Replace
Right Side Drive Outer:	Tracmax	1.74mm - Must Replace
Left Side Drive Inner:	Tracmax	2.70mm
Left Side Drive Outer:	Tracmax	1.42mm - Must Replace
Spare Wheel:	N/A	N/A

Reconditioning Needed:

Brake Wear warning light (Sensor) - +/- R25

4X Tyres need replacing (Roadworthy Relevant) - R7600 +/-

Spare Wheel - R1900 +/-

General Service Due - R6300 +/-

Rear roof panel has water damage (Needs to be quoted)

Left rear A/C Duct panel missing (Needs to be quoted)

A/C needs to be re-gassed - R1000 +/-

Roadworthy & COF + Brake Test - R1500 +/-

Visible dent on the top of left rear door (Needs to be quoted)

Visible dents on passenger door (Needs to be quoted)

Slight Injector misfire on 1 injector (Needs to be quoted -Very Good pulling power, slight vibration on idling.

Right rear park light not working (Roadworthy Relevant) - R50

No 100 Sticker (Roadworthy Relevant) - R80

Right mirror cracked (Roadworthy Relevant) - Needs to be quoted	
Window control buttons missing, Left + Right (Needs to be quoted)	
Rear Mercedes-Benz Badge Missing (Needs to be quoted)	
Minor dents and scratches all round (Needs to be quoted)	
No Spare key	

Optional Extras:

Dekra Condition Report	R 5500
Police Clearance (Only for Export)	R 3500

Things to note:

Please read our Terms & Conditions carefully provided in the Buyers Registration Form.

TAG Commercial will not be held responsible for Licensing, Registration or Roadworthing of any Vehicle unless stated otherwise in writing.

All vehicles listed by TAG Commercial are sold as-is, in their current condition at the time of sale.

TAG Commercial makes no representations or warranties regarding mechanical condition, mileage, or overall state of vehicles listed.

Buyers are responsible for conducting their own inspections and due diligence on the condition of the vehicle before purchase.

TAG Commercial assumes no responsibility for the repair, maintenance, or correction of any damage, defect, or wear-and-tear on any vehicle sold.

Sales Representatives:

Calvin Van Der Merwe	079 063 0977
Sipho 'Henry' Kumalo	071 327 2052 / 073 312 8600
Ray Karshagen	076 021 9104